



SERVICE INFORMATION BULLETIN


Bulletin: 98-11-03

Date: 3/98

Subject: MAIN HVAC DRAIN TUBE DUCKBILL (KAZOO)

Models Affected: VEHICLES WITH VIN 178369 AND ABOVE

Starting with VIN 178369, vehicles are being built without the kazoo and retaining clamp on the drain tube of the main HVAC unit (See Figure 1). The kazoo has been removed to eliminate the possibility of moisture backing up into the HVAC unit. Leave the drain tube open and do not install a kazoo.



7-P11-001.1

Figure 1: Drain Tube Kazoo Location.

